



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification
Restricted

Title : Failure of Turbine Blades of
AI-20 M Engine in AN-12 Aircraft

Document No.
PD MT 8713

Date of issue: Mar 87

Author(s) : S.Radhakrishnan, R.V.Krishnan,
A.C.Raghuram, R.Rangaraju,
M.A.Venkataswamy & V.Ramachandran

Contents 7 pages
incl. 6 figures

Division : Materials Science

No. of copies: 12

**External
participation** :

NAL Project No.
MT-1-167

Sponsor :

Sponsor's Project No.

Approval : A.C.Raghuram

Remarks :

Keywords : AN-12 aircraft, AI-20 M engine, Turbine blades,
Fatigue failure

Abstract :

A turbine blade of the last stage of an AI-20 M engine failed in service. The failure was due to a fatigue crack initiated at the trailing edge, at the root portion, just above the fir tree region.